Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

CERTIFICATE OF CORRECTION	
PATENT NO. : 7,014,144 B2	Page <u>1</u> of <u>1</u>
APPLICATION NO.: 10/789,827	
ISSUE DATE : March 21, 2006	
INVENTOR(S) : Jeffrey M. HEIN	
Comey W. Film	
It is certified that an error appears or errors appear in the above-identified patent and the is hereby corrected as shown below:	at said Letters Patent
Column 12, line 10, "flaw" should be changed toflow	

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Ingrassia Fisher & Lorenz 7150 E. Camelback Rd., Suite 325 Scottsdale, Arizona 85251

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U. S. Patent: 7,014,144 B2 Examiner: T. Dinh

Issued: March 21, 2006 Group: 3644

Inventor(s): Jeffrey M. HEIN Docket No. H0001402

For: DUAL ACTION INLET DOOR AND METHOD FOR USE THEREOF

CERTIFICATE OF CORRECTION UNDER 37 CFR 1.322

Attn: Certificate of Corrections Branch

P.O. Box 1450

Alexandria, VA 22313-1450

Sir:

Please correct the above-identified patent by issuing a Certificate of Correction for a Patent Office mistake under Rule 1.322 as follows:

Column 12, line 10, "flaw" should be changed to --flow--.

This error occurred through the fault of the Patent Office and no fee is involved. The issuance of a Certificate of Correction under Rule 1.322 is therefore considered proper.

Respectfully submitted,

Date: February 7, 2007 /PAULD.AMROZOWICZ/

Ingrassia Fisher & Lorenz, P.C.

By: Paul D. Amrozowicz

Attorney for Applicant(s)

Reg. No. 45,264 Tel. (480) 385-5060